

# Oil Field Environmental Incident Summary

**Incident:** 20150727091931      **Date/Time of Notice:** 07/27/2015 09:19

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** SMOKEY 13-7-19-13H

**Field Name:** PEMBROKE

**Well File #:** 24788

**Date Incident:** 7/25/2015      **Time Incident:** 20:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 149

**Rng:** 98

**Sec:** 7

**Qtr:**

**Location Description:** North of the facility. An area approximately 21' x 12' just over the property owner's fence.

**Submitted By:** Daniel Ryan

**Received By:**

**Contact Person:** Daniel Ryan  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	32	Barrels			32	barrels
<b>Brine</b>	5	Barrels			5	barrels

**Other**

**Description of Other Released Contaminant:**

None.

**Inspected:**

**Written Report Received:** 1/8/2016

**Clean Up Concluded:** 10/28/2015

**Risk Evaluation:**

None noted.

**Areal Extent:**

Majority of the spill remained on location. Approx. 1 gal. misted off location. Area was 21' x 12'.

**Potential Environmental Impacts:**

To be determined.

**Action Taken or Planned:**

The wells and treater were secured and the treater was dumped of remaining fluid. A vac truck was called in to remove standing fluid

**Wastes Disposal Location:** An approved location

**Agencies Involved:**

**Updates**

---

**Date:** 7/27/2015    **Status:** Reviewed - Follow-up Required    **Author:** Suess, Bill

**Updated Oil Volume:** 32.00 barrels

**Updated Salt Water Volume:** 5.00 barrels

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release left the well pad. Environmental risk has not been determined at this time. Followup is required.

---

**Date:** 7/29/2015    **Status:** Inspection    **Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On location 7/29/15, at 12:40pm. Impacted area off site was to the North of well pad on a side hill which consisted of pasture land. There is a fence on opposite side of hill. A discussion with the contact revealed that the lease area goes to that fence line. There was no impact seen outside of fenced area. Impact off well pad remained within leased area. No further follow-up required.