

# Oil Field Environmental Incident Summary

**Incident:** 20150803194340      **Date/Time of Notice:** 08/03/2015 19:43

**Responsible Party:** MUREX PETROLEUM CORPORATION

**Well Operator:** MUREX PETROLEUM CORPORATION

**Well Name:** JACOB DANIEL 25-36H-RE

**Field Name:** SANISH

**Well File #:** 16839

**Date Incident:** 7/31/2015      **Time Incident:** 15:30

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 154

**Rng:** 91

**Sec:** 36

**Qtr:** SW SW

**Location Description:**

**Submitted By:** William Jansky

**Received By:**

**Contact Person:** Shannon Holter  
363 N. Sam Houston Pkwy. E.  
Suite 200  
HOUSTON, TX 77060

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Barrels			0	gallons

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/20/2016

**Clean Up Concluded:** 1/1/2016

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Stuffing box tightened. Bioremediation applied to impacted area.

**Wastes Disposal Location:** None

**Agencies Involved:**

**Updates**

---

**Date:** 8/4/2015    **Status:** Reviewed - Assigned to Other Agency    **Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a stuffing box leak, remained on location according to the report. NDIC retains oversight.