

Oil Field Environmental Incident Summary

Incident: 20150804121835 **Date/Time of Notice:** 08/04/2015 12:18

Responsible Party: STATOIL OIL & GAS LP

Well Operator: STATOIL OIL & GAS LP

Well Name: JAROLD 25-36 3TFH

Field Name: TODD

Well File #: 23091

Date Incident: 8/3/2015 **Time Incident:** 16:00

Facility ID Number:

County: WILLIAMS

Twp: 155 **Rng:** 101 **Sec:** 25 **Qtr:**

Location Description:

Submitted By: Derick McFadden

Received By:

Contact Person: Derrick McBride
6300 BRIDGE POINT PKY, BLDG 2
SUITE 500
AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	10	barrels	10	barrels		
--------------	----	---------	----	---------	--	--

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None, all fluids were contained inside a lined containment.

Areal Extent:

Potential Environmental Impacts:

None, all fluids were contained inside a lined containment.

Action Taken or Planned:

Spill was contained inside a lined containment. Remediation of contaminated material has already begun. Action plan is to require more frequent inspections of gaskets on facilities.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 8/4/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve piping connection leak, remained on location according to the report. NDIC retains oversight.