

Oil Field Environmental Incident Summary

Incident: 20150808113959 **Date/Time of Notice:** 08/08/2015 11:39

Responsible Party: Hess Tioga Gas Plant LLC

Well Operator:

Well Name: 16" Hofflund Extension - Wet Gas Low Pressure Line

Field Name: HOFFLUND

Well File #:

Date Incident: 8/7/2015 **Time Incident:** 13:30

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 95

Sec: 9

Qtr:

Location Description: 154N 95W Sec 9 - 16" Hofflund Extension - Wet Gas Low Pressure Line

Submitted By: Alex Beach

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1.3 Mile

Distance Nearest Water Well: 1.3 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Unknown

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Wet gas

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

Estimated 10' by 15' area

Potential Environmental Impacts:

An estimated 10' by 15' area of topsoil has been impacted. There is no data to support any additional potential environmental impacts at this time.

Action Taken or Planned:

A North Dakota One Call was initiated. Field Operations is working to isolate the line.

Wastes Disposal Location: At an approved waste disposal facility

Agencies Involved:

Updates

Date: 8/10/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pipeline leak, impacted topsoil according to the report. No release amount was given, and it is unknown as to the release being contained. More followup needed to determine amount and potential receptors for the release.

Date: 9/2/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 11:27 9/2/2015.

Area excavated with little impacts to surrounding areas. No sign of spilled material at the time of inspection.

No followup is necessary.

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received an email from Hess's consultant with an attachment that assessed the release site. The results showed that there were remaining impacts to soil near the release. The report states that they are going to further assess the area by advancing soil borings and collecting samples. After the assessment, another site assessment report will be prepared and forwarded to the NDDoH. Continued communications and more followup needed depending on second assessment of the area. Email and report added to the folder.