

Oil Field Environmental Incident Summary

Incident: 20150813174700 **Date/Time of Notice:** 08/13/2015 17:47

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: ARLEY 21X-18B

Field Name: GRINNELL

Well File #: 20906

Date Incident: 8/12/2015 **Time Incident:** 15:00

Facility ID Number:

County: WILLIAMS

Twp: 154 **Rng:** 96 **Sec:** 18 **Qtr:**

Location Description:

Submitted By: JORDAN WOLF

Received By:

Contact Person: KAYLAN DIRKX
P.O Box 6506
321 22nd Ave. E.
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	Gallons	20	Gallons		
Brine	10	Barrels	10	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None- spill contained in lined metal containment and on facility soil.

Areal Extent:

Potential Environmental Impacts:

None- spill contained in lined metal containment and on facility soil.

Action Taken or Planned:

All free liquids were recovered and disposed of at an approved disposal facility. The impacted soil was removed and put into a yellow soil bin.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 8/14/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, remained on constructed well site according to the report. NDIC retains oversight.