

Oil Field Environmental Incident Summary

Incident: 20150824070545 **Date/Time of Notice:** 08/24/2015 07:05

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: VAN HOOK SECTION 13 NWNW CENTRAL FACILITY

Field Name: PARSHALL

Well File #:

Date Incident: 8/23/2015 **Time Incident:** 08:58 **Facility ID Number:** 216997-01

County: MOUNTRAIL **Twp:** 152 **Rng:** 91 **Sec:** 13 **Qtr:** NW NW

Location Description:

Submitted By: Keith Kallberg

Received By:

Contact Person: Keith Kallberg
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3.5	Barrels	3.5	Barrels	3.5	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/1/2015

Clean Up Concluded: 8/23/2015

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The water transfer was stopped and the tank was isolated, a vac truck was called in and removed the fluid in the tank and on the backside of the tank along with the rain water, 7 bbls of fluid were removed from the berm.

Wastes Disposal Location: Fluids were taken to SWD.

Agencies Involved: MHA & TAT

Updates

Date: 8/25/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained within diking according to the report. NDIC retains oversight.