

Oil Field Environmental Incident Summary

Incident: 20150824190404 **Date/Time of Notice:** 08/24/2015 19:04

Responsible Party: Targa Resources

Well Operator:

Well Name: Clarks Creek compressor station

Field Name:

Well File #:

Date Incident: 8/24/2015 **Time Incident:** 14:18

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 94

Sec: 7

Qtr:

Location Description: Head south on Hwy. 22 from the tee of Hwy 22 & 23 for 5 miles. Clarks Creek compressor station is situated 0.5 miles west of Hwy 22

Submitted By: Mitchell W. Anderson

Received By:

Contact Person: David Low
1939 125 Avenue NW
Watford City, ND 58854

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no immediate health hazards associated with this release event.

Areal Extent:

50'L x 50'W

Potential Environmental Impacts:

There were no adverse environmental impacts to the environment associated with this event.

Action Taken or Planned:

The pump to the tank was immediately shut off upon discovery of the tank overflow.

Wastes Disposal Location: Impacted soils will be transported to a licensed and approved landfill.

Agencies Involved: MHA Nation, McKenzie County LEPC

Updates

Date: 8/25/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Harries, Alison

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

This incident was also filed under the General category. See General Environmental Incident ID 3875 for updates.