

Oil Field Environmental Incident Summary

Incident: 20150825214959 **Date/Time of Notice:** 08/25/2015 21:49

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: WOOD 21X-25AXB

Field Name: TRUAX

Well File #: 24232

Date Incident: 8/25/2015 **Time Incident:** 16:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 98

Sec: 25

Qtr:

Location Description:

Submitted By: Scot Richardson

Received By:

Contact Person: Scot Richardson
P.O Box 6506
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Barrels	25	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Vacuum truck will collect free liquids and return to tank. Vacuum truck will collect impacted materials and transport them to an approved disposal facility.

Wastes Disposal Location: To be determined.

Agencies Involved:

Updates

Date: 8/26/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location within the dikes. NDIC retains oversight.