

Oil Field Environmental Incident Summary

Incident: 20150916155953 **Date/Time of Notice:** 09/16/2015 15:59

Responsible Party: Quale Trucking, LLC

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P BIBLER 155-99-16-31-7-16H3A

Field Name: STOCKYARD CREEK

Well File #: 29696

Date Incident: 9/16/2015 **Time Incident:** 08:55

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 99

Sec: 31

Qtr:

Location Description:

Submitted By: Ross Chaffin

Received By:

Contact Person: Ross Chaffin
PO Box 970
New Town, ND 58763

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	3	Barrels	3	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 11/25/2015

Clean Up Concluded: 9/21/2015

Risk Evaluation:

low

Areal Extent:

Potential Environmental Impacts:

low, the spill was contained inside of the tank battery.

Action Taken or Planned:

Driver immediately stopped the flow of oil from his tank and trailer, and started to suck up the oil on the ground. Drivers will be required to wire down or strap down the camlock ears on there hoses so they can't pop lose.

Wastes Disposal Location: At a approved facility unknown at this time

Agencies Involved:

Updates

Date: 9/16/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.