

Oil Field Environmental Incident Summary

Incident: 20150923085539 **Date/Time of Notice:** 09/23/2015 08:55

Responsible Party: Wendt & Sons Oilfield Service

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: BOHMBACH 3-35H

Field Name: ELM TREE

Well File #: 21490

Date Incident: 9/22/2015 **Time Incident:** 10:00

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 94

Sec: 23

Qtr:

Location Description:

Submitted By: Todd Senescall

Received By:

Contact Person: Justin Grimm
10359 Hwy 200
Killdeer, ND 58640

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels	2	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

location soil

Action Taken or Planned:

standing liquid sucked up. ABS deployed and recovered contaminated soil.
Insure accuracy of load indicator prior to and during filling.

Wastes Disposal Location: Liquid - SWD
soil - TBD

Agencies Involved: Sam Skurupey, NDIC inspector (voicemail)

Updates

Date: 9/23/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, remained on location according to the report. NDIC retains oversight.