

# Oil Field Environmental Incident Summary

**Incident:** 20151001143042      **Date/Time of Notice:** 10/01/2015 14:30

**Responsible Party:** Hess Tioga Gas Plant LLC

**Well Operator:** HESS TIOGA GAS PLANT LLC

**Well Name:** Pipeline

**Field Name:**

**Well File #:**

**Date Incident:** 9/24/2015      **Time Incident:** 14:15

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 95

**Sec:** 9

**Qtr:** SW SE

**Location Description:** 14" Hofflund Extension - Pipeline Right of Way (ROW) - LAT/Long: 48  
19.335N 102 56.249 W

**Submitted By:** Alex Beach

**Received By:**

**Contact Person:** Jason Henry  
3015 16th Street SW, Suite 20  
Minot, ND 58701

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 2 Mile

**Distance Nearest Water Well:** 2 Mile

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Pipeline ROW

**Reported to NRC:** No

<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

**Other**

**Description of Other Released Contaminant:**

Natural Gas and Condensate. The quantity has not yet been determined. The normal operating pressure is 50 PSI.

**Inspected:**

**Written Report Received:** 2/18/2016

**Clean Up Concluded:** 10/14/2016

**Risk Evaluation:**

There is no immediate risk to report at this time.

**Areal Extent:**

The impacted area is approximately 100 Sq. Feet.

**Potential Environmental Impacts:**

There are potential environmental impacts to the material surrounding the released natural gas and condensate.

**Action Taken or Planned:**

The ND One-Call process was initiated. The landowner will be notified. The impacted area will be excavated to expose the damaged portion of the pipe. The damaged portion will be fixed. The impacted material will be disposed of at an approved waste disposal facility.

**Wastes Disposal Location:** All recovered waste will be disposed of at an approved waste disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 10/1/2015    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release on pipeline ROW. Follow-up is required.

---

**Date:** 12/17/2015    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived at legal description location at 11:00. Parked at an approach and observed the site. Loaded lat and long points into Garmin hand-held GPS, which showed the location to be more than 10 miles north of the legal location. Could not determine if there was an area impacted near the legal location due to vastness of area and snow covering the ground. It appeared a pipeline running from the northwest towards the southeast had been buried near the location. More followup needed.

---

**Date:** 12/21/2015 **Status:** Correspondence

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Spoke with the company contact via phone and was informed that the cleanup contractor had collected confirmation samples before backfilling the location. Sample results should be available for review by next month. More followup needed.