

Oil Field Environmental Incident Summary

Incident: 20151012094821 **Date/Time of Notice:** 10/12/2015 09:48

Responsible Party: OASIS PETROLEUM NORTH AMERICA LLC

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: HAZEL 6192 43-23T

Field Name: FOOTHILLS

Well File #: 28969

Date Incident: 10/11/2015 **Time Incident:** 10:00

Facility ID Number:

County: BURKE

Twp: 161

Rng: 92

Sec: 23

Qtr:

Location Description: Spill occurred in triplex building & seeped out of door

Submitted By: Tim Christianson

Received By:

Contact Person: Tim Christianson
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	1	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Ground contaminataion

Areal Extent:

Potential Environmental Impacts:

Oil in soil

Action Taken or Planned:

Sucked up oil that was there on ground. Plan on pressure washing out building & sucking up what we wash out. May need to remove some soil depending on soil tests. Also will put oil absorbent on ground.

Wastes Disposal Location: Put oil we sucked off ground in our salt water tank

Agencies Involved:

Updates

Date: 10/12/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained on facility site according to the report. NDIC retains oversight.