

Oil Field Environmental Incident Summary

Incident: 20151013150214 **Date/Time of Notice:** 10/13/2015 15:02

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: CHSU MARY 41-31SH 14

Field Name: CEDAR HILLS

Well File #: 14079

Date Incident: 9/18/2015 **Time Incident:** 10:30

Facility ID Number:

County: BOWMAN

Twp: 131

Rng: 104

Sec: 31

Qtr:

Location Description: 75 yards south of the Erickson TB. (Inadvertently reported as being on location internally thus late reporting)

Submitted By: Josh Cuppy

Received By:

Contact Person: Josh Cuppy
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels	0.5	Barrels	0.5	barrels
Brine	1	Barrels	1	Barrels	1	barrels

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 10/19/2015 **Clean Up Concluded:** 9/25/2015

Risk Evaluation:

NONE

Areal Extent:

Leak was contained on pipeline ROW.

Potential Environmental Impacts:

NONE

Action Taken or Planned:

Shut in well. Impacted soil was removed during repair.

Wastes Disposal Location: Soil was put in containers and will be taken to the LMS landfill.

Agencies Involved:

Updates

Date: 10/13/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pipeline leak, impacted topsoil along a pipeline ROW according to the report. The report also stated the date of release as 9/18/15. More follow-up needed to determine reporting delay and to assure proper cleanup of the site.

Date: 10/29/2015 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume: 0.50 barrels

Updated Salt Water Volume: 1.00 barrels

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 11:00 a.m. The weather was sunny with light winds from the NE. Temperature was 32 degrees F.

The area of impact is located south of the well pad road. GPS N46.13081, W 103.72478. The impacted area measures about 20 feet long by 10 feet wide. The soil has been dug up and the material replaced. In addition, vegetation is starting to grow in the area that was disturbed. There was no visible stained soil on site.

Conducted soil conductivity readings.

Background:

3" - 381uS

6" - 342uS

GPS - N46.13121, W103.72479

Impacted area:

3" - 442uS

6" - 475uS

9" - 392uS

12" - 493uS

No additional followup needed.