

# Oil Field Environmental Incident Summary

**Incident:** 20151014063730      **Date/Time of Notice:** 10/14/2015 06:37

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** VAN HOOK 34-1319H

**Field Name:** PARSHALL

**Well File #:** 29054

**Date Incident:** 10/13/2015      **Time Incident:** 08:45

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 152

**Rng:** 91

**Sec:** 13

**Qtr:** NW SW

**Location Description:** Van Hook sec 30 NWSW Central Facility

**Submitted By:** Keith Kallberg

**Received By:**

**Contact Person:** Keith Kallberg  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	3	Barrels	3	Barrels	3	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/8/2016

**Clean Up Concluded:** 10/13/2015

**Risk Evaluation:**

Low

**Areal Extent:**

NA

**Potential Environmental Impacts:**

Low

**Action Taken or Planned:**

The transfer pump was shutdown stopping the release. Vac truck was used to remove the free fluid and the affected area will be flushed with fresh water and fluids removed.

**Wastes Disposal Location:** SWD

**Agencies Involved:** MHA & TAT

**Updates**

---

**Date:** 10/14/2015 **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to equipment failure, stayed within the diking according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA.