

Oil Field Environmental Incident Summary

Incident: 20151014150333 **Date/Time of Notice:** 10/14/2015 15:03
Responsible Party: Enable Midstream
Well Operator: XTO ENERGY INC.
Well Name: LUNDIN FEDERAL 31X-9
Field Name: NORTH FORK **Well File #:** 17629
Date Incident: 10/14/2015 **Time Incident:** 05:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 149 **Rng:** 97 **Sec:** 9 **Qtr:** NW NE
Location Description: LACT Unit located on the Lundin Federal 31X-9 well pad

Submitted By: John Launius **Received By:**
Contact Person: John Launius
P.O Box 6501
Englewood, CO 80155

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels	1	Barrels	15	barrels
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 12/18/2015 **Clean Up Concluded:** 10/23/2015

Risk Evaluation:

Low impact to well pad ground surface. All free liquids on the ground have been removed.

Areal Extent:

Potential Environmental Impacts:

Low environmental impact. Impacted area is approximately 20 feet by 30 feet. Depth of soil impact ranges from 2 - 6 inches.

Action Taken or Planned:

All free standing liquids were removed. A one call notification has been issued. Due to underground utilities in the impacted area no excavation will occur until the one call has been cleared. Excavation & pad restoration work will begin on 10/16/15 @ 1:00 PM (estimated time necessary for one call process to be complete). Our environmental response contractor has been notified and will provide clean up services as directed. The contaminated soil will be excavated and placed in roll off containers. Further environmental actions include profile and disposal of the recovered material in an approved landfill. Kaylan Dirx with XTO (EH&S Dept.) was notified by phone on 10/14/15 of the incident and response actions.

Wastes Disposal Location: The impacted soil will be disposed at the Chimney Butte Landfill, 1217 Highway 85, Fairfield, ND 58627. The produced water will be disposed at the Fairfield Treating Plant, 1488 Highway 85, Fairfield, ND 58627.

Agencies Involved:

Updates

Date: 10/14/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on constructed well site according to the report. NDIC retains oversight.