

Oil Field Environmental Incident Summary

Incident: 20151015134630 **Date/Time of Notice:** 10/15/2015 13:46

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P WOOD 154-98-14-22-15-3H3

Field Name: TRUAX

Well File #: 29812

Date Incident: 10/14/2015 **Time Incident:** 13:45

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 98

Sec: 22

Qtr:

Location Description:

Submitted By: Corissa Zimmer

Received By:

Contact Person: Corissa Zimmer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

Spilled	Units	Recovered	Units
---------	-------	-----------	-------

Followup	Units
----------	-------

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/22/2015

Clean Up Concluded: 10/15/2015

Risk Evaluation:

None noted

Areal Extent:

Potential Environmental Impacts:

None noted

Action Taken or Planned:

The lease operator extinguished the fire. Whiting immediately sent out an email to all field employees to check recirculation pumps and check all lovejoy fitting connections.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 10/15/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Tintes Schiwal, Emily

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The release was contained on the constructed well site. NDIC Oil & Gas retains oversight.