

Oil Field Environmental Incident Summary

Incident: 20151015144400 **Date/Time of Notice:** 10/15/2015 14:44

Responsible Party: H & P Drilling

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: Bridger 7-14H2

Field Name: RATTLESNAKE POINT

Well File #: 31842

Date Incident: 10/15/2015 **Time Incident:** 00:20

Facility ID Number:

County: DUNN

Twp: 146

Rng: 96

Sec: 14

Qtr: NW NE

Location Description:

Submitted By: Todd Senescall

Received By:

Contact Person: James Sharp
3214 110K Ave. SW
Dickinson, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	10	Barrels	9.5	Barrels		

Description of Other Released Contaminant:

OMB mud

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

pressurized fluid

Areal Extent:

Potential Environmental Impacts:

location soil

Action Taken or Planned:

Standing fluid was sucked up. Floor dry spread to absorb additional fluid. Contaminated soil will be recovered when the equipment is moved. Expansion joint was replaced.

Wastes Disposal Location: tbd

Agencies Involved: Tamara Cook, NDIC Inspector (left message)

Updates

Date: 10/15/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Tintes Schiwal, Emily

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The release was contained to the constructed well site. NDIC Oil & Gas retains oversight.