

Oil Field Environmental Incident Summary

Incident: 20151016150411 **Date/Time of Notice:** 10/16/2015 15:04

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: TENNECO 4-17 SWD

Field Name: MCKINNEY

Well File #: 11083

Date Incident: 10/10/2015 **Time Incident:** 1030

Facility ID Number:

County: RENVILLE

Twp: 161

Rng: 86

Sec: 17

Qtr:

Location Description: CTB SWD house.

Submitted By: Scott Hunskor

Received By:

Contact Person: Scott Hunskor
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	90	Barrels	90	Barrels	90	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/26/2015

Clean Up Concluded: 10/20/2015

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Shut pump down, isolate leak, tanker truck to load up fluid inside dike, scrape up dirty soil and cover with clean gravel.

Wastes Disposal Location: Fluid in tanks on location, and any solids to 3 sided tank to be later hauled to clean harbor.

Agencies Involved:

Updates

Date: 10/27/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.