

Oil Field Environmental Incident Summary

Incident: 20151020084328 **Date/Time of Notice:** 10/20/2015 08:43

Responsible Party: ConocoPhillips Company

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: CCU PLYMOUTH 21-29TFH

Field Name: CORRAL CREEK

Well File #: 31937

Date Incident: 10/19/2015 **Time Incident:** 15:00

Facility ID Number:

County: DUNN

Twp: 147

Rng: 94

Sec: 29

Qtr: NW NW

Location Description: from roundabout south of Killdeer, follow Hwy. 22 north for 13.2 miles to CCU Main Access Road. Turn right and follow for 5.6 miles, Turn right (east) and follow for 1 mile. Turn left at black gates. Turn right at stop sign and follow for 2.4 miles to Y in road. Stay to right and follow for .2 miles to location.
Note Combination for electric gate is 1234.

Submitted By: James Smith

Received By:

Contact Person: James Smith

PO BOX 51810

MIDLAND, TX 79710-1810

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	20	Barrels	20	Barrels		

Description of Other Released Contaminant:

Water based drilling mud breached to surface approximately 200' from wellbore.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None.

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Control drill remaining wellbores on this pad to minimize the ECD during the suspected interval.

Wastes Disposal Location: N/A

Agencies Involved:

Updates

Date: 10/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.