

Oil Field Environmental Incident Summary

Incident: 20151021071227 **Date/Time of Notice:** 10/21/2015 07:12

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PAUL 1-19H

Field Name: PARSHALL

Well File #: 16628

Date Incident: 10/20/2015 **Time Incident:** 11:30

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 89

Sec: 19

Qtr:

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	5	Barrels	5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/8/2016

Clean Up Concluded: 10/21/2015

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Vac truck was called immediately to remove standing liquids, a crew will be replacing gasket material and cleanup will begin.

Wastes Disposal Location: The liquids were placed back into tanks and solids tbd

Agencies Involved:

Updates

Date: 10/21/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location according to the report. NDIC retains oversight.