

# Oil Field Environmental Incident Summary

**Incident:** 20151025093436      **Date/Time of Notice:** 10/25/2015 09:34

**Responsible Party:** WESCO OPERATING, INC.

**Well Operator:** WESCO OPERATING, INC.

**Well Name:** BNRR 1-7

**Field Name:** BICENTENNIAL

**Well File #:** 6308

**Date Incident:** 10/24/2015      **Time Incident:** 09:15

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 145

**Rng:** 103

**Sec:** 7

**Qtr:**

**Location Description:** spill occurred at pump house at tank battery

**Submitted By:** Dave Weinert

**Received By:**

**Contact Person:** Dave Weinert  
PO BOX 1650  
120 S. DURBIN STREET  
CASPER, WY 82602

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	34	Barrels	33	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

low

**Areal Extent:**

contained on location

**Potential Environmental Impacts:**

location soils only

**Action Taken or Planned:**

Pump was shut off. Spilled liquid picked up by vac truck and returned to tanks. Soil may be excavated if needed.

**Wastes Disposal Location:** Recovered oil was placed back into production tanks. If soil is removed it will be taken to licensed disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 10/26/2015 **Status:** Reviewed - Assigned to Other Agency

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to equipment failure, remained on location according to the report. NDIC retains oversight.