

# Oil Field Environmental Incident Summary

**Incident:** 20151111123838      **Date/Time of Notice:** 11/11/2015 12:38

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** SCHROEDER 1 SWD

**Field Name:** STONEVIEW

**Well File #:** 90138

**Date Incident:** 11/10/2015      **Time Incident:** 16:31

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 160

**Rng:** 95

**Sec:** 34

**Qtr:**

**Location Description:**

**Submitted By:** Timothy Ilse

**Received By:**

**Contact Person:** Kelly Thomas  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pump Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	18	Barrels	18	Barrels		
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

5 ft. by 10 ft. area outside of containment

**Potential Environmental Impacts:**

Well site soil

**Action Taken or Planned:**

Check valve was replaced, contaminated material recovered and taken to disposal.

**Wastes Disposal Location:** R360

**Agencies Involved:** Called John Rumppe @ 12:36 PM on 11/11/2015

**Updates**

---

**Date:** 11/12/2015 **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a pump leak, remained on constructed well site according to the report. NDIC retains oversight.