

# Oil Field Environmental Incident Summary

**Incident:** 20151126103418      **Date/Time of Notice:** 11/26/2015 10:34

**Responsible Party:** WPX Energy

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** VAN HOOK GATERING SYSTEM

**Field Name:** VAN HOOK

**Well File #:**

**Date Incident:** 11/26/2015      **Time Incident:** 03:00      **Facility ID Number:** 550551-27

**County:** MOUNTRAIL      **Twp:** 151      **Rng:** 92      **Sec:** 20      **Qtr:**

**Location Description:** Release is located on the pad facility.

**Submitted By:** Robert Raup

**Received By:**

**Contact Person:** Robert Raup  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	220	Barrels			220	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 12/29/2016      **Clean Up Concluded:** 6/17/2016

## **Risk Evaluation:**

There is no immediate risk at this time as the flow of produced water has been stopped. All impacts appear to have remained on location.

## **Areal Extent:**

The areal extent of the incident is contained to the facility site.

**Potential Environmental Impacts:**

Impacts to water and soils off location are not likely at this time. Crews are on-site to determine a remedial course of action. A One Call will be performed and crews will remediate and dispose of impacted materials.

**Action Taken or Planned:**

A remedial course of action is being determined. All impacted materials will be removed from location. The release was discovered at 03:00 and the flow of produced water was immediately stopped.

**Wastes Disposal Location:** Prairie Disposal - Tioga, ND

**Agencies Involved:** MHA Energy  
BIA

**Updates**

---

**Date:** 11/27/2015 **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank overflow, remained on the facility site according to the report. NDIC retains oversight.