

# Oil Field Environmental Incident Summary

**Incident:** 20151208154310      **Date/Time of Notice:** 12/08/2015 15:43

**Responsible Party:** ONEOK Rockies Midstream

**Well Operator:** ONEOK ROCKIES MIDSTREAM

**Well Name:** Bennett Creek CS Pipeline

**Field Name:**

**Well File #:**

**Date Incident:** 12/8/2015      **Time Incident:** 09:15

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 146

**Rng:** 99

**Sec:** 20

**Qtr:**

**Location Description:**

**Submitted By:** Byron Skaley

**Received By:**

**Contact Person:** Byron Skaley  
2700 Lincoln Ave SE

Sidney, MT 59270

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.3 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Pipeline ROW

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Gallons	5	Gallons		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No immediate risk

**Areal Extent:**

**Potential Environmental Impacts:**

No potential environmental impact

**Action Taken or Planned:**

soil was hauled off to disposal facility

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 12/8/2015    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a pipeline leak, impacted topsoil along a pipeline right-of-way according to the report. Further followup needed.

---

**Date:** 4/21/2016    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 9:45. 42 degrees F, sunny, SE wind 0-10 mph. Drove county road through Section 20, but could not determine incident location due to GPS coordinates not being available on report. Will follow up with company contact to get more precise location directions. Another NDDoH inspector has spoken to the company contact and will follow up next week during inspections.

---

**Date:** 4/25/2016    **Status:** Correspondence

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Spoke with contact Byron Skaley and received GPS coordinates for release location. GPS coordinates for the release are 47.452142, -103.312767. Google Earth shows the release to be on the west side of 128th Ave SW, south of the road leading to the farmstead. More follow-up needed.