

Oil Field Environmental Incident Summary

Incident: 20151221174327 **Date/Time of Notice:** 12/21/2015 17:43

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: AN-BRENNA-153-94-3130H

Field Name: ANTELOPE

Well File #:

Date Incident: 12/21/2015 **Time Incident:** 05:00

Facility ID Number: 228370-01

County: MCKENZIE

Twp: 152

Rng: 95

Sec: 3

Qtr: NE NE

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Troy Brunsell
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1000 Feet

Distance Nearest Water Well: 1000 Feet

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels			5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/4/2016

Clean Up Concluded: 12/31/2015

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

Potential Environmental Impacts:

Approximately 0.5 bbl of crude oil left the site and potentially impacted the areas that it touched.

Action Taken or Planned:

The landowner will be notified. The impacted material will be cleaned up and disposed of. A root cause analysis will be conducted.

Wastes Disposal Location: The impacted material will be cleaned up and disposed of at an approved waste disposal facility.

Agencies Involved:

Updates

Date: 12/22/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, some of the release left the well pad. Further followup required.

Date: 12/30/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 12:10. 9 degrees F, light snow, NW wind 5-10 mph. Walked perimeter of well pad and took photos. Did not observe any petroleum staining of visible vegetation that was above 4-5 inches of snowcover. Identifying sign at the entrance showed the location to be 3130H-1 instead of 3130H-8, which is stated on the report. More followup needed to determine correct location and cleanup report.