

Oil Field Environmental Incident Summary

Incident: 20151222175310 **Date/Time of Notice:** 12/22/2015 17:53

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: GRAVGAARD 13-24-1H

Field Name: MIDWAY

Well File #: 22521

Date Incident: 12/22/2015 **Time Incident:** 11:00

Facility ID Number:

County: WILLIAMS

Twp: 157

Rng: 96

Sec: 24

Qtr:

Location Description: Approximately 15 gallons of oil misted WNW off location onto landowner property affecting an area 300' x 50'.

Submitted By: JORDAN WOLF

Received By:

Contact Person: KAYLAN DIRKX
P.O Box 6506
WILLISTON, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	6	Barrels			5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/17/2016

Clean Up Concluded: 5/5/2016

Risk Evaluation:

Minor risk- ground is frozen and cleanup commenced quickly.

Areal Extent:

Approx. 15 gallons of oil misted WNW off location affecting an area 300' x 50'.

Potential Environmental Impacts:

Minimal- a small amount misted off location onto landowner property. The ground is frozen- no absorption is anticipated. All free liquids were quickly recovered and returned to the production tanks.

Action Taken or Planned:

The well was shut in by the lease operator after the spill discovery. The free liquids were recovered and returned to the production tanks. Any impacted soil will be removed and hauled to an approved waste disposal facility. Recovered oil amount will be updated when cleanup is complete.

Wastes Disposal Location: R360

Agencies Involved:

Updates

Date: 12/23/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release did not remain on the well pad. Further followup necessary.

Date: 12/30/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

12/30/2015 at 14:15, on location. Walked west and north sides of field bordering wellpad. No visible staining underneath snow. No further followup required.