

Oil Field Environmental Incident Summary

Incident: 20160104162013 **Date/Time of Notice:** 01/04/2016 16:20

Responsible Party: NEWFIELD PRODUCTION COMPANY

Well Operator: NEWFIELD PRODUCTION COMPANY

Well Name: FLECK 150-100-12-1-2H

Field Name: SANDROCKS

Well File #: 27733

Date Incident: 1/3/2016 **Time Incident:** 00:30

Facility ID Number:

County: MCKENZIE

Twp: 150 **Rng:** 100 **Sec:** 12 **Qtr:** SW SE

Location Description:

Submitted By: Tim Eaton

Received By:

Contact Person: Tim Eaton
363 N Sam Houston Pkwy E Ste. 100
Houston, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	2	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/22/2016

Clean Up Concluded: 1/6/2016

Risk Evaluation:

No immediate risks

Areal Extent:

Contained on location

Potential Environmental Impacts:

Oil sprayed on to on site snow. Potentially some oil reached on site soils.

Action Taken or Planned:

Open the choke a little more to prevent freezing.

Wastes Disposal Location: All oil was vacuumed up with the snow and was disposed of at Indian Hills disposal facility.

Agencies Involved:

Updates

Date: 1/5/2016 **Status:** Reviewed - Assigned to Other Agency **Author:** Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on the well pad. NDIC has oversight.