

# Oil Field Environmental Incident Summary

**Incident:** 20160107160348      **Date/Time of Notice:** 01/07/2016 16:03

**Responsible Party:** CRESCENT POINT ENERGY U.S. CORP.

**Well Operator:** CRESCENT POINT ENERGY U.S. CORP.

**Well Name:** CPEUSC PAOPAO 35-26-158N-100W

**Field Name:** DUBLIN

**Well File #:** 21860

**Date Incident:** 1/7/2016      **Time Incident:** 09:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 157      **Rng:** 100      **Sec:** 2      **Qtr:**

**Location Description:** Primary leak contained to well site, but light misting of oil extended to standing snow on adjacent property.

**Submitted By:** Chris Del Hierro

**Received By:**

**Contact Person:** Scott VanDeWoestyne  
555 17TH STREET, SUITE 1800  
DENVER, CO 80202

**General Land Use:** Cultivated

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	21	Barrels	21	Barrels	21	barrels
<b>Brine</b>	9	Barrels	9	Barrels	9	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 4/29/2016

**Clean Up Concluded:** 4/25/2015

**Risk Evaluation:**

None

**Areal Extent:**

Approximately 50 feet by 400 feet of misted surface impact extending on well pad and offsite.

**Potential Environmental Impacts:**

Misted impacts to surface soil and standing snow.

**Action Taken or Planned:**

Well was temporarily shut-in and wellhead packing is being replaced. All standing fluids recovered and placed back into production. Surface soil is being excavated, misted area of snow scraped; soil and snow being hauled to Secure 13 Mile disposal facility.

**Wastes Disposal Location:** Surface soil is being excavated, misted area of snow scraped; soil and snow being hauled to Secure 13 Mile disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 1/7/2016    **Status:** Reviewed - Follow-up Required    **Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release was not contained within the well pad perimeter. Further followup needed.

---

**Date:** 1/12/2016    **Status:** Inspection    **Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

1/12/2016 at 11:30, on location. Mist went north-northwest from wellhead, crossing over lease road north of wellpad and into wheat stubble field further to the north. Field and edges of lease road have been scraped. No visible staining in scraped area, but there is faint staining visible in snow around power pole and path used to access the field. Residual staining should naturally attenuate. No further follow-up required.