

# Oil Field Environmental Incident Summary

**Incident:** 20160125080629      **Date/Time of Notice:** 01/25/2016 08:06

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** MATHEWSON 3-30H

**Field Name:** OLIVER

**Well File #:** 24013

**Date Incident:** 1/24/2016      **Time Incident:** 09:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 157

**Rng:** 98

**Sec:** 19

**Qtr:**

**Location Description:** Borrow ditch adjacent to location.

**Submitted By:** Patrick Skillestad

**Received By:**

**Contact Person:** Patrick Skillestad  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	10	Gallons	10	Gallons	10	gallons

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 9/20/2016

**Clean Up Concluded:** 1/26/2016

**Risk Evaluation:**

None

**Areal Extent:**

Very lightly misted a 30 ft x 50 ft area off location in the adjacent borrow ditch.

**Potential Environmental Impacts:**

Snow off location, gravel in flare pit.

**Action Taken or Planned:**

Lightly misted snow was scraped up and put into flare pit, then flare pit was sucked out with vac truck.

**Wastes Disposal Location:** TBD

**Agencies Involved:**

**Updates**

---

**Date:** 1/25/2016    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release impacted area off location. Followup is required.

---

**Date:** 1/27/2016    **Status:** Inspection

**Author:** Wax, Pete

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 16:40, off site 17:00. 36 degrees, clear 20-30 mph NW wind. Nearest water is a creek 30 meters to the south. Spray exited pad to the south and landed on the south edge and ditch of the access road. Snow was removed and placed in flare dike. There is a small amount of staining on road but no evidence of crude oil in ditch where the snow was collected.

---

**Date:** 3/10/2016    **Status:** Correspondence

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Bill Suess sent a No Further Action letter dated March 10, 2016.