

# Oil Field Environmental Incident Summary

**Incident:** 20160125084752      **Date/Time of Notice:** 01/25/2016 08:47

**Responsible Party:** MUREX PETROLEUM CORPORATION

**Well Operator:** MUREX PETROLEUM CORPORATION

**Well Name:** STATE RAAUM 1-15

**Field Name:** FORTUNA

**Well File #:** 7828

**Date Incident:** 1/22/2016      **Time Incident:** 10:00

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 162      **Rng:** 101      **Sec:** 15      **Qtr:** SW SW

**Location Description:**

**Submitted By:** William Jansky

**Received By:**

**Contact Person:** Shannon Holter  
363 N. Sam Houston Pkwy. E.  
Suite 200  
HOUSTON, TX 77060

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1.9 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	7	Barrels	7	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

Oil misted approximately 250 yards off site to the northwest. 250 yards long by 75 yards wide.

**Potential Environmental Impacts:**

None. 1 BBL or less was off site in field. The mist was on snow which was plowed onto facility site for removal.

**Action Taken or Planned:**

The well was shut in and treater drained. A vacuum truck was called to recover pooled fluids. The contaminated snow was plowed onto facility. The snow will be loaded into flat tanks and allowed to melt. Water will be placed into production tanks for disposal.

**Wastes Disposal Location:** Production tanks for water, solids if any will be taken to Secure disposal 13 mile corner.

**Agencies Involved:**

**Updates**

---

**Date:** 1/25/2016    **Status:** Reviewed - Follow-up Required    **Author:** Crowder, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release impacted area off location. Followup is required.

---

**Date:** 1/27/2016    **Status:** Inspection    **Author:** Wax, Pete

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 14:10, off site 14:55. 37 degrees, wind 25-40 mph NW, clear. Site is still wet, and snow is piled on well pad (photos taken). Spray entered soybean field to the south. Snow has been scraped off an area approximately 75 meters by 300 meters leading to the north. Walked entire area completely cleared of snow. Found no indication of crude oil on surface of soybean field. Collected many photographs. Needs follow-up to ensure that the bean field is not impacted from salt.

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

The company representative sent in lab results and photos of the samples with GPS coordinates. The lab results show no traces of oil in the samples. The supplied information will be in the corresponding folder, and a follow-up inspection can be conducted after the snow melts to ensure there are no visible impacts.