

# Oil Field Environmental Incident Summary

**Incident:** 20160125151415      **Date/Time of Notice:** 01/25/2016 15:14

**Responsible Party:** WESCO OPERATING, INC.

**Well Operator:** WESCO OPERATING, INC.

**Well Name:** KOSTELECKY 44-29

**Field Name:** DOBSON BUTTE

**Well File #:** 9322

**Date Incident:** 1/22/2016      **Time Incident:** 17:00

**Facility ID Number:**

**County:** STARK

**Twp:** 139

**Rng:** 96

**Sec:** 29

**Qtr:**

**Location Description:** A treater upset caused oil to be sent out to the flare.

**Submitted By:** Scott Kerr

**Received By:**

**Contact Person:** Scott Kerr  
PO BOX 1650  
120 S. DURBIN STREET  
CASPER, WY 82602

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.2 Mile

**Distance Nearest Water Well:** 0.4 Mile

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Barrels	1.5	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

Crude oil

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No immediate risk

**Areal Extent:**

Spill contained within flare pit/location

**Potential Environmental Impacts:**

Minor soil staining on location

**Action Taken or Planned:**

free liquid and stained snow is being collected and placed into a tank. Root cause of spill is still being investigated.

**Wastes Disposal Location:** Stained snow and liquids being placed into a tank and will be recycled back into system.

**Agencies Involved:**

**Updates**

---

**Date:** 1/25/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release remained on location according to the report. NDIC retains oversight.