

Oil Field Environmental Incident Summary

Incident: 20160128091709 **Date/Time of Notice:** 01/28/2016 09:17

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: CHICAGO 3-26H

Field Name: BANKS

Well File #: 23048

Date Incident: 1/27/2016 **Time Incident:** 09:30

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 99

Sec: 26

Qtr:

Location Description:

Submitted By: NATE STANHOPE

Received By:

Contact Person: NATE STANHOPE
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 8 | Barrels | 8 | Barrels | | |
| Brine | 2 | Barrels | 2 | Barrels | | |

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

60 ft. x 20 ft. lightly misted snow outside of containment

Potential Environmental Impacts:

Location soil

Action Taken or Planned:

The standing fluid inside containment was sucked up and options for dealing with the impacted soil inside containment are currently being evaluated. All of the lightly misted snow outside of containment will be scraped up and removed.

Wastes Disposal Location: A licensed disposal facility

Agencies Involved:

Updates

Date: 1/28/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.