

Oil Field Environmental Incident Summary

Incident: 20160211142426 **Date/Time of Notice:** 02/11/2016 14:24

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: USA-VOLKMANN 1-X

Field Name: CHARLSON

Well File #: 6287

Date Incident: 2/10/2016 **Time Incident:** 09:30

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 95

Sec: 7

Qtr:

Location Description:

Submitted By: Shawn Dahl

Received By:

Contact Person: Shawn Dahl
2732 Hwy 85 North
Alexander, ND 58831

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 8 | Barrels | 7 | Barrels | 7 | barrels |

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/17/2016

Clean Up Concluded: 5/26/2016

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

the spill was contained within the dike. the oil was cleaned up and will be placed back into the production tank. All other impacted material will be removed.

Wastes Disposal Location: The oil will be placed back into production tanks. Impacted material will be hauled to an approved disposal facility.

Agencies Involved:

Updates

Date: 2/11/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained within diking according to the report. NDIC retains oversight.