

Oil Field Environmental Incident Summary

Incident: 20160213101957 **Date/Time of Notice:** 02/13/2016 10:19

Responsible Party: Crestwood Midstream Partners LP

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 2/12/2016 **Time Incident:** 17:00

Facility ID Number:

County: DUNN

Twp: 148

Rng: 92

Sec: 18

Qtr: NW NW

Location Description: On the Pipeline Right of Way, just to the south site of the Whiting Skunk Creek 4-18 pad.

Note: this is not on the pad, entirely on Pipeline ROW.

Submitted By: Joshua Swann

Received By:

Contact Person: Joshua Swann
10702 HWY 73
Keene, ND 58847

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risks

Areal Extent:

Potential Environmental Impacts:

No potential impacts

Action Taken or Planned:

Clean up team arrived the evening of the incident, to hydrovac impacted snow and soil.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 2/16/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was in a pipeline right of way. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.