

Oil Field Environmental Incident Summary

Incident: 20160216161659 **Date/Time of Notice:** 02/16/2016 16:16

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: CCU Section 10 CTB

Field Name: CEDAR CREEK

Well File #:

Date Incident: 2/16/2016 **Time Incident:** 06:00

Facility ID Number: 402509-02

County: BOWMAN

Twp: 130

Rng: 107

Sec: 10

Qtr: NE NE

Location Description: On location

Submitted By: Josh Cuppy

Received By:

Contact Person: Josh Cuppy
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Release fluid ran for a short distance on location where it pooled

Potential Environmental Impacts:

None

Action Taken or Planned:

Shut the test cock valve. Called in water truck to flush and recover the impacted area. Impacted area will be back dragged.

Wastes Disposal Location: Fluids will be recovered back into Section 10. Not recovering soil

Agencies Involved: BLM

Updates

Date: 2/16/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC takes oversight.