

Oil Field Environmental Incident Summary

Incident: 20160220114813 **Date/Time of Notice:** 02/20/2016 11:48

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: RS-R HARSTAD-157-90- 2029H-1

Field Name: CLEAR WATER

Well File #: 18046

Date Incident: 2/19/2016 **Time Incident:** 13:30

Facility ID Number:

County: MOUNTRAIL

Twp: 157

Rng: 90

Sec: 20

Qtr:

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Troy Brunsell
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 500 Feet

Distance Nearest Water Well: 500 Feet

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine					0	barrels
Other	35	Gallons			35	gallons

Description of Other Released Contaminant:

Emulsion

Inspected:

Written Report Received: 3/4/2016

Clean Up Concluded: 2/27/2016

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

241' by 72' of the release impacted areas offsite

Potential Environmental Impacts:

There are potential environmental impacts to the impacted areas offsite

Action Taken or Planned:

Arrangements were made for the impacted material to be cleaned up and disposed of. The landowner will be notified of the release.

Wastes Disposal Location: The impacted material will be cleaned up and disposed of at an approved waste disposal facility.

Agencies Involved:

Updates

Date: 2/22/2016 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Date: 3/1/2016 **Status:** Inspection

Author: Torgerson, Brad

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site on March 1, 2016. It appeared vegetation and top soil had been excavated just east of the treater. Crude oil was observed on the well location, but not off the well pad location. It appeared cleanup of location was necessary.

Date: 3/8/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 16:30. Area on hill next to heater treater looks to be scraped up. Recommend coming back to assess vegetation growth. Photos can be found in the report folder.