

Oil Field Environmental Incident Summary

Incident: 20160224111637 **Date/Time of Notice:** 02/24/2016 11:16

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: LINDVIG 9

Field Name: CAMP

Well File #: 11613

Date Incident: 2/24/2016 **Time Incident:** 08:30

Facility ID Number:

County: MCKENZIE

Twp: 152 **Rng:** 101 **Sec:** 9 **Qtr:**

Location Description: On location

Submitted By: Josh Cuppy

Received By:

Contact Person: Brian Ehrmantraut
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	3	Barrels	3	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/29/2016

Clean Up Concluded: 2/25/2016

Risk Evaluation:

None

Areal Extent:

Contained.

Potential Environmental Impacts:

None

Action Taken or Planned:

Shut in well. Vac truck recovered fluids.

Wastes Disposal Location: Liquids were put into tank on location.

Agencies Involved: BLM

Updates

Date: 2/25/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.