

Oil Field Environmental Incident Summary

Incident: 20160225084658 **Date/Time of Notice:** 02/25/2016 08:46

Responsible Party: SM ENERGY COMPANY

Well Operator: SM ENERGY COMPANY

Well Name: RINI 1X-16HB

Field Name: POE

Well File #: 31066

Date Incident: 2/24/2016 **Time Incident:** 10:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 100

Sec: 16

Qtr: NE NE

Location Description:

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine	4.5	Barrels	3	Barrels	3	barrels
Other					0	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/24/2016

Clean Up Concluded: 2/25/2016

Risk Evaluation:

N/A.

Areal Extent:

N/A.

Potential Environmental Impacts:

N/A.

Action Taken or Planned:

Contractor has accepted responsibility for the spill and associated cleanup.

Wastes Disposal Location: Recovered fluid and contaminated soil will be taken to an approved disposal.

Agencies Involved:

Updates

Date: 2/25/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.