

# Oil Field Environmental Incident Summary

**Incident:** 20160302100917      **Date/Time of Notice:** 03/02/2016 10:09

**Responsible Party:** STATOIL OIL & GAS LP

**Well Operator:** STATOIL OIL & GAS LP

**Well Name:** TRENTON SWD 1

**Field Name:** ROSEBUD

**Well File #:** 90145

**Date Incident:** 3/1/2016      **Time Incident:** 22:20

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 102

**Sec:** 35

**Qtr:**

**Location Description:** Trenton SWD site in saltwater offload lane # 1

**Submitted By:** Derrick Dion

**Received By:**

**Contact Person:** Derrick Dion  
6300 BRIDGE POINT PKY, BLDG 2  
SUITE 500  
AUSTIN, TX 78730

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	20	Barrels	20	Barrels		

**Description of Other Released Contaminant:**

None

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No danger to environment. contained on facility site.

**Areal Extent:**

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Site and are of offload lane # 1 was cleaned by super-vac truck. Tank trailer removed from service by contractor management, until required repairs are made to trailer, tested, and verified.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 3/2/2016    **Status:** Reviewed - Assigned to Other Agency    **Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release remained on location. NDIC retains oversight.