

# Oil Field Environmental Incident Summary

**Incident:** 20160310120404      **Date/Time of Notice:** 03/10/2016 12:04

**Responsible Party:** Lime Rock Resources

**Well Operator:** OXY USA INC.

**Well Name:** FISHER STATE 1-21-16H-142-97

**Field Name:** WILLMEN

**Well File #:** 19438

**Date Incident:** 3/9/2016      **Time Incident:** 17:55

**Facility ID Number:**

**County:** DUNN

**Twp:** 142

**Rng:** 97

**Sec:** 21

**Qtr:**

**Location Description:**

**Submitted By:** Robyn Espinoza

**Received By:**

**Contact Person:** Robyn Espinoza  
PO BOX 2000  
DICKINSON, ND 58601

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Barrels			0	barrels
<b>Brine</b>	1	Barrels			0	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 4/1/2016

**Clean Up Concluded:** 3/17/2016

**Risk Evaluation:**

Contaminated surface material

**Areal Extent:**

**Potential Environmental Impacts:**

Contaminated surface material

**Action Taken or Planned:**

The well was shut in to prevent further release, a crew has been dispatched to replace the gasket and remove all contaminated surface materials.

**Wastes Disposal Location:** Chimney Butte

**Agencies Involved:**

**Updates**

---

**Date:** 3/10/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to equipment failure, remained on constructed well site according to the report. NDIC retains oversight.