

# Oil Field Environmental Incident Summary

**Incident:** 20160311111100      **Date/Time of Notice:** 03/11/2016 11:11

**Responsible Party:** WESCO OPERATING, INC.

**Well Operator:** WESCO OPERATING, INC.

**Well Name:** PETERSON G 1

**Field Name:** SMITH

**Well File #:** 12740

**Date Incident:** 3/10/2016      **Time Incident:** 12:00

**Facility ID Number:**

**County:** RENVILLE

**Twp:** 160

**Rng:** 86

**Sec:** 29

**Qtr:**

**Location Description:** Flowline leak between pumping unit and battery

**Submitted By:** Scott Kerr

**Received By:**

**Contact Person:** Scott Kerr  
PO BOX 1650  
120 S. DURBIN STREET  
CASPER, WY 82602

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1.2 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	20	Barrels	20	Barrels	20	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/23/2017

**Clean Up Concluded:** 5/6/2016

**Risk Evaluation:**

None

**Areal Extent:**

Arial extent limited to 40 ft x 40 ft

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Impacted soils will be excavated and staged for disposal. Flowline will be repaired.

**Wastes Disposal Location:** TBD

**Agencies Involved:**

**Updates**

---

**Date:** 3/11/2016    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, cultivated cropland off the well pad was impacted by a release of oil.

More followup needed.

---

**Date:** 4/7/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 4/7/2016.

Impacted soil scraped up and awaiting disposal. Impacts in natural area north of well location, north of road in Section 20, Township 160, Range 86.

Sampling necessary to ensure proper cleanup. Samples are also needed from the nearby wetland to ensure no material entered the wetland.

More follow-up is necessary.