

Oil Field Environmental Incident Summary

Incident: 20160315163459 **Date/Time of Notice:** 03/15/2016 16:34

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: ANNAPOLIS 6-29H1

Field Name: DOLLAR JOE

Well File #: 29290

Date Incident: 3/15/2016 **Time Incident:** 06:00

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 97

Sec: 20

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Gallons	1	Gallons	1	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/17/2016

Clean Up Concluded: 3/15/2016

Risk Evaluation:

None

Areal Extent:

150x30 feet off the south side of location.

Potential Environmental Impacts:

Top soil and vegetation

Action Taken or Planned:

Soil samples will be taken to determine impact and appropriate clean-up actions taken.

Wastes Disposal Location: TBD

Agencies Involved: Notified Mark Bins NDIC by phone on 3/21/2016 at 08:30 AM CT.

Updates

Date: 3/15/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 2 gallons of oil were not contained and released onto topsoil and vegetation. More follow-up needed.

Date: 3/16/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 3/16/2016.

Slight spray off of the SE corner of the well pad. Impacts slightly discernible off of location.

No follow-up is necessary.