

Oil Field Environmental Incident Summary

Incident: 20160316102915 **Date/Time of Notice:** 03/16/2016 10:29

Responsible Party: Hunt Oil Company

Well Operator: HUNT OIL COMPANY

Well Name: WEFLEN 1-27H

Field Name: PARSHALL

Well File #: 17425

Date Incident: 3/15/2016 **Time Incident:** 15:00

Facility ID Number:

County: MOUNTRAIL

Twp: 154 **Rng:** 90 **Sec:** 27 **Qtr:** SW SE

Location Description: Due to high winds, spray had fallen to the ground with a visible spray area (170'x80') off location. Spray coverage off location is very light with individual droplets readily identifiable.

Submitted By: Andrew Dittus

Received By:

Contact Person: Andrew Dittus
1900 NORTH AKARD STREET
DALLAS, TX 75201-2300

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.8 Mile

Distance Nearest Water Well: 0.8 Mile

Type of Incident: Other - List Under Desc of Cause below

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Gallons				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/11/2016

Clean Up Concluded: 3/18/2016

Risk Evaluation:

Minimal risk. Top spoil will be reclaimed Friday March 18th.

Areal Extent:

170' x 80' area covered with individual droplets.

Potential Environmental Impacts:

Top soil is the only contaminated area and is scheduled to get reclaimed Friday March 18th.

Action Taken or Planned:

All fluids on location were immediately removed via vacuum truck. JMAC is schedule to reclaim the affected top soil Friday March 18th. Due to the amount of paraffin in the well we didn't want to risk running wireline downhole as there would be a possibility of getting stuck so the decision was made to utilize a mudbox and vacuum truck to recover the fluid when breaking joints. Unfortunately, due to high winds and larger displacement volumes, fluid displaced from the top of the pipe and the wind carried individual droplets off location.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/16/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a blowout, impacted topsoil off the well pad. More follow-up needed.

Date: 4/8/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 10:18 on 4/8/2016.

Impacted area tilled and scraped up with no remaining signs of impact at the location.

No additional follow-up is necessary.