

Oil Field Environmental Incident Summary

Incident: 20160325100705 **Date/Time of Notice:** 03/25/2016 10:07

Responsible Party: SM ENERGY Company

Well Operator: SM ENERGY COMPANY

Well Name: MOLANDER 22-15-161-99H 1XC

Field Name: BURG

Well File #: 26776

Date Incident: 3/23/2016 **Time Incident:** 20:30

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 99

Sec: 27

Qtr: NE NW

Location Description:

Submitted By: Gary Bjerke

Received By:

Contact Person: Gary Bjerke
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine	2.4	Barrels	2	Barrels	2.4	barrels
Other					0	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/22/2016

Clean Up Concluded: 12/1/2012

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

2 barrels salt water recovered. Soil remediated

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/30/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location within the diking system. NDIC retains oversight.