

Oil Field Environmental Incident Summary

Incident: 20160325125627 **Date/Time of Notice:** 03/25/2016 12:56

Responsible Party: Oneok Rockies Midstream

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Stateline Gas Plant

Field Name:

Well File #:

Date Incident: 3/25/2016 **Time Incident:** 06:30

Facility ID Number:

County: WILLIAMS

Twp: 155 **Rng:** 103 **Sec:** 21 **Qtr:**

Location Description: 15071 56th Street NW
Williston, ND 588011

Submitted By: Levi Weltikol

Received By:

Contact Person: Levi Weltikol
2700 Lincoln Ave SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	1	Gallons				

Description of Other Released Contaminant:

Natural Gas Condensate

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk

Areal Extent:

Potential Environmental Impacts:

No environmental impacts

Action Taken or Planned:

Impacted soil removed. equipment isolated for repair.

Wastes Disposal Location: Certified Landfill

Agencies Involved:

Updates

Date: 3/28/2016 **Status:** Reviewed - No Action Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, a small amount of condensate was released and immediately cleaned up. No follow-up is necessary.