

Oil Field Environmental Incident Summary

Incident: 20160412102526 **Date/Time of Notice:** 04/12/2016 10:25

Responsible Party: Black Hills Trucking

Well Operator: NEWFIELD PRODUCTION COMPANY

Well Name: SAND CREEK FEDERAL 153-96-23-14-2H

Field Name: KEENE

Well File #: 21591

Date Incident: 4/12/2016 **Time Incident:** 08:00

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 96

Sec: 26

Qtr: NW NW

Location Description: Sand Creek Federal 153-96-23-14-2H battery

Submitted By: Bob Dundas

Received By:

Contact Person: Bob Dundas

P.O. Box 757

Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels				

Brine

Other

Description of Other Released Contaminant:

Crude Oil

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

no immediate risks have been identified

Areal Extent:

spill is contained onsite

Potential Environmental Impacts:

A small area of soils on site were impacted.

Action Taken or Planned:

A cleanup contractor will be dispatched to excavate the impacted soils and haul to a permitted disposal facility. The excavated area will then be backfilled with cleanfill materials.

Wastes Disposal Location: TBA

Agencies Involved:

Updates

Date: 4/12/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, remained on constructed well site according to the report. NDIC retains oversight.