

# Oil Field Environmental Incident Summary

**Incident:** 20160506153638      **Date/Time of Notice:** 05/06/2016 15:36

**Responsible Party:** Black Hills Trucking Co.

**Well Operator:** SM ENERGY COMPANY

**Well Name:** KLAMM 13-10H

**Field Name:** SIVERSTON

**Well File #:** 17952

**Date Incident:** 5/6/2016      **Time Incident:** 11:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150

**Rng:** 97

**Sec:** 10

**Qtr:** SW SW

**Location Description:** Klamm 13-10 H battery

**Submitted By:** Bob Dundas

**Received By:**

**Contact Person:** Bob Dundas  
PO BOX 7168  
BILLINGS, MT 59103-7168

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.5	Barrels				

**Brine**

**Other**

**Description of Other Released Contaminant:**

Crude Oil

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No immediate risks are present

**Areal Extent:**

Soils around truck were impacted.

**Potential Environmental Impacts:**

Surface soils onsite were impacted.

**Action Taken or Planned:**

Driver shut down loading operations. Clean up crews have been contacted and are in route. Impacted soils will be excavated and managed offsite at a permitted disposal facility.

**Wastes Disposal Location:** To be determined.

**Agencies Involved:**

**Updates**

---

**Date:** 5/6/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a truck overflow, was contained to the facility site according to the report. NDIC retains oversight.