

# Oil Field Environmental Incident Summary

**Incident:** 20160510111415      **Date/Time of Notice:** 05/10/2016 11:14

**Responsible Party:** Nuverra

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** GNR FEDERAL 15-22H

**Field Name:** PAINTED WOODS

**Well File #:** 24165

**Date Incident:** 5/9/2016      **Time Incident:** 23:03

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 153      **Rng:** 102      **Sec:** 10      **Qtr:** SE SW

**Location Description:**

**Submitted By:** Bill Cheney

**Received By:**

**Contact Person:** Bill Cheney  
4900 hwy 2 & 52 W  
Minot, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Soil and Water

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	20	Barrels				
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Soil and ground

**Areal Extent:**

Approximately 90feet by 60 feet

**Potential Environmental Impacts:**

Soil and ground

**Action Taken or Planned:**

Vac trailers are cleaning up surface water and heavy equipment will be coming when one call is cleared. Soil testing is being done on location. The contaminated material will be disposed of at the proper disposal.

**Wastes Disposal Location:** Nuverra Terrafficient disposal

**Agencies Involved:**

**Updates**

---

**Date:** 5/10/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release remained on location according to the report. NDIC retains oversight.