

Oil Field Environmental Incident Summary

Incident: 20160606142818 **Date/Time of Notice:** 06/06/2016 14:28
Responsible Party: PETRO HARVESTER OPERATING COMPANY, LLC
Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC
Well Name: SCHULTZ 1 SWDW
Field Name: FLAXTON **Well File #:** 10406
Date Incident: 6/5/2016 **Time Incident:** 17:00 **Facility ID Number:**
County: BURKE **Twp:** 163 **Rng:** 91 **Sec:** 14 **Qtr:** SW NW
Location Description:

Submitted By: Gary Watson **Received By:**
Contact Person: Mark Bonnie
5851 LEGACY CIRCLE
SUITE 500
PLANO, TX 75024

General Land Use: Cultivated **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 7000 Feet
Distance Nearest Water Well: 7000 Feet

Type of Incident: Valve/Piping Connection Leak

	Spilled	Units	Recovered	Units	Reported to NRC:	Followup	Units
Oil					No	0	barrels
Brine	5	Barrels	5	Barrels		5	barrels
Other						0	barrels

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 6/13/2016 **Clean Up Concluded:** 6/10/2016

Risk Evaluation:
No explosive or immediate health hazard risk.

Areal Extent:
3 ft x 1 ft - off the well site pad to the east - estimated at 1/2 bbl of produced fluid

Potential Environmental Impacts:

No impact to surface water or ground water. An estimated 1/2 bbl of produced fluid was released off of the well site pad.

Action Taken or Planned:

While carrying out clean up operations at the Schultz 1 SWDW battery (110406) - a line leak near the injection well head was identified. NDIC Field Inspector Jim Potts was notified telephonically. The surface owner will be identified and notified regarding the release. The released fluids were vacuumed up and the affected soil will be scraped up, collected and disposed of at an approved disposal facility. The injection line elbow will be replaced and the entire injection line will be pressure tested to 500 psig prior to placing into service. The area around the injection wellhead will be diked to prevent released fluids from leaving the well site pad.

Wastes Disposal Location: An approved disposal facility.

Agencies Involved:

Updates

Date: 6/6/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report the release was not contained to the well pad. Further follow-up is needed.

Date: 6/9/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12:57 6/9/2016.

No sign of remaining impacts at the time of inspection. Recent work has been done on the location with new berms being built on location.

No Follow up is necessary.