

Oil Field Environmental Incident Summary

Incident: 20160607114331 **Date/Time of Notice:** 06/07/2016 11:43

Responsible Party: LIME ROCK RESOURCES III-A, L.P.

Well Operator: LIME ROCK RESOURCES III-A, L.P.

Well Name: JOHN KINNE 1-27-34H-142-98

Field Name: SNOW

Well File #: 24716

Date Incident: 6/7/2016 **Time Incident:** 06:30

Facility ID Number:

County: DUNN

Twp: 142

Rng: 98

Sec: 22

Qtr: SW SE

Location Description: Oil and gas production site.

Submitted By: Kate Forsting

Received By:

Contact Person: Dustin Tscher
1111 BAGBY, SUITE 4600
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	7	Barrels			0	barrels

Brine

Other

Description of Other Released Contaminant:

None.

Inspected:

Written Report Received: 6/22/2016

Clean Up Concluded: 6/7/2016

Risk Evaluation:

No immediate risk.

Areal Extent:

The release was contained on the production location.

Potential Environmental Impacts:

The release was contained on the production location. There were no potential environmental impacts.

Action Taken or Planned:

Upon discovery, filling operations were immediately shut down. Impacted soils were scraped up by Steier, Oilfield Contract Services, and will be disposed of according to NDIC waste disposal guidelines.

Wastes Disposal Location: R-360 Disposal Facility (Chimney Butte).

Agencies Involved: Robin Espinosa, 701-264-4923, Lime Rock Resources.

Updates

Date: 6/7/2016 **Status:** Reviewed - Assigned to Other Agency **Author:** Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report the release was contained to the well pad. NDIC takes oversight.